

DAMAGE ASSESSMENT FORM

Building Name KROME RESIDENCE

Address 17845 S.W. 296 STREET

City (or Vicinity) and County DADE COUNTY. MIAMI, FL

Owner ALLEMAN, Jeffrey & w Medora 247-1349

Date of Construction 1920 Folio No. 30-7801-000-0580

Primary Use

- | | | | |
|---|---|--|--------------------------------------|
| <input checked="" type="checkbox"/> Residential (1-2 units) | <input type="checkbox"/> Residential 3+ units | <input type="checkbox"/> Office Building | <input type="checkbox"/> School |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Mixed | <input type="checkbox"/> Church | <input type="checkbox"/> Lodge |
| <input type="checkbox"/> Industrial/Warehouse | <input type="checkbox"/> Hotel/Motel | <input type="checkbox"/> Bank | <input type="checkbox"/> Other _____ |

Description

- | | | |
|--|--------------------------------|--------------------------|
| <input checked="" type="checkbox"/> Freestanding | <input type="checkbox"/> Row | No. of Stories <u>—1</u> |
| <input type="checkbox"/> Basement | <input type="checkbox"/> Attic | No. Chimney(s) <u>—1</u> |
| <input type="checkbox"/> Electrical System _____ | | |

Construction Type

- | | | | |
|--|---|--|-----------------------------------|
| <input type="checkbox"/> Masonry Bearing Wall | <input type="checkbox"/> Veneer/Steel Frame | <input checked="" type="checkbox"/> Wood Frame | <input type="checkbox"/> Concrete |
| <input type="checkbox"/> Veneer/Concrete Frame | <input type="checkbox"/> Concrete Unit | <input type="checkbox"/> Other _____ | |

Surface Covering

- | | | |
|--------------------------------------|---|--------------------------------|
| <input type="checkbox"/> Stucco | <input checked="" type="checkbox"/> Wood Siding (lap/other) | <input type="checkbox"/> Stone |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Roof _____ | |

Foundation

- ☒ Concrete Slab ☐ Block ☐ Limestone Rubble ☐ Other _____ ☐ Unknown

Geological Natural of Site

- ☐ Bedrock ☒ Soil/Sand ☐ Fill ☐ Other _____ ☐ Unknown

Historical Designation

- ☐ National Register ☐ Local ☐ Local District ☐ State
☒ Dade County Historic Survey (Rating) 2 ☐ None ☐ Unknown

Failing Hazards

	Hazards	No Apparent Hazard	Unknown	Comments
Chimney(s)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	_____
Floors	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	_____
Roof Structure	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	_____
Equipment	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Trees	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	_____

KROME

Failing Hazards (Con't)

	Hazards	No Apparent Hazard	Unknown	Comments
Parapet/Cornice	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>caves / facias</u>
Ornamentation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>none</u>
Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

Fire Hazards

☒ Electrical should be inspected ☐ Debris ☐ Gas

Damage Observations

Rating Scale

None (0%) 0

Slight (1-10%) 1

Moderate (11-40%) 2-3-4

Severe (41-60%) 5

Total (over 60%) 6

Not Observed: NO

Not Applicable: NA

	%	Comments
Exterior Walls	1	
Frame (General Condition)	0	
Frame Members	0	
Frame Connections	0	
Roof Framing	1	
Roof Covering	20	
Foundation	0	
Chimney(s)	0	
Doors	0	
Windows and Shutters	1	
Porch	0	
Downspouts and Gutters	NA	
Interior Bearing/Shear Walls	0	
Partitions (Nonbearing)	1	
Floor(s)	1	
Stair(s)	NA	
Glass	1	
Mechanical Equipment	NO	
Electrical Equipment	NO	
Garden and Trees	40	
Fences and Garden Walls	NA	
Walkways and Sidewalks	0	
Other: <u>Driveway(s)</u>	30	<u>Rock Damage</u>
Total Damage	15%	

KRAME

Overall Structural Assessment

- ☐ No Damage or Easily Repairable
☒ Damage Repairable
☐ Damage Will Require Massive Repair/Reconstruction

Recommendations for Further Inspection SEEMS TO BE IN
RELATIVELY GOOD CONDITION

Recommendations for Immediate Actions ROOF NEEDS TO BE REDONE

Recommendations for Future Repair Work CEDAR SHAKES WILL NEED TO
BE REMOVED BEFORE METAL TILE WILL BE ABLE
TO BE REPLACED; ^(Interior) CONCRETE WALLS WILL NEED
SOME TREATMENT

Recommendations for Immediate Stabilization ROOF IS CURRENTLY
LEAKING


Salvageable Materials

- ☐ Wood siding (lap, other) ☐ Structural members (Dade County Pine)
☐ Fixtures/hardware ☐ Other _____

Landscape Assessment

Site Sketch:

(Significant landscape features, large old trees, (standing/down) walls, paths, groves (type)).



Comments:

LANDSCAPE LOSS
INCLUDES MANY VARIETY OF PALMS
AVOCADO : MANGO

Inspector(s) R. C. D. Agency/Team _____ Date 9.4.92
Photographs or Video (Roll and Numbers) _____

KROME

